
FIG. 1











FIG. 5

















7/26

F I G. 10

	Fx	Fy	Fz
Rx1	_	0	<u> </u>
Rx2	+	0	+
R x 3	-	.0	+
Rx4	+	0	_
		•	
Ry1	0	. –	. —
Ry2	0	+	+
Ry 3.	.0		+.
Ry4	0	+	_
Rz 1		. 0	
Rz 2	+	0	+
Rz3	_	0	+
Rz4	. +	· 0	. —

FIG. 11




FIG. 12





FIG. 13



F1G.14





FIG. 15



F I G. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28





FIG. 29



F1G. 30a





FIG. 30b



F I G. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35





FIG. 36






FIG. 40





FIG. 41






FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51

<u>300</u>




FIG. 52

